



UNITED STATES PATENT AND TRADEMARK OFFICE

COMMISSIONER FOR PATENTS
UNITED STATES PATENT AND TRADEMARK OFFICE
WASHINGTON, D.C. 20231
www.uspto.gov



Bib Data Sheet

CONFIRMATION NO. 8111

SERIAL NUMBER 09/974,967	FILING DATE 10/11/2001 RULE	CLASS 243 714	GROUP ART UNIT 2184	ATTORNEY DOCKET NO. AUS920010564US1
APPLICANTS Douglas Craig Bossen, Austin, TX; Daniel James Henderson, Georgetown, TX; Raymond Leslie Hicks, Rochester, MN; Alongkorn Kitamorn, Austin, TX; David Otto Lewis, Rochester, MN; Thomas Alan Liebsch, Rochester, MN;				
** CONTINUING DATA *****				
** FOREIGN APPLICATIONS *****				
IF REQUIRED, FOREIGN FILING LICENSE GRANTED ** 11/13/2001				
Foreign Priority claimed <input type="checkbox"/> yes <input checked="" type="checkbox"/> no 35 USC 119 (a-d) conditions met <input type="checkbox"/> yes <input checked="" type="checkbox"/> no <input type="checkbox"/> Met after Allowance Verified and Acknowledged		STATE OR COUNTRY TX	SHEETS DRAWING 10	TOTAL CLAIMS 36
Examiner's Signature <i>Michael Markham</i>		INDEPENDENT CLAIMS 3		
ADDRESS Duke W. Yee Carstens, Yee & Cahoon, LLP P.O. Box 802334 Dallas, TX 75380				
TITLE Apparatus and method of repairing a processor array for a failure detected at runtime				
FILING FEE RECEIVED 1028	FEES: Authority has been given in Paper No. _____ to charge/credit DEPOSIT ACCOUNT No. _____ for following:		<input type="checkbox"/> All Fees <input type="checkbox"/> 1.16 Fees (Filing) <input type="checkbox"/> 1.17 Fees (Processing Ext. of time) <input type="checkbox"/> 1.18 Fees (Issue) <input type="checkbox"/> Other _____ <input type="checkbox"/> Credit	